



5


BUILDING SAFETY CERTIFICATE


This is to Certify that Agarwal Public School (Run by Agarwal Charitable Trust) at Khasara No. 84/1, 84/4, 84/5, Bicholi Mardana Road, Indore (M.P.) is having proper <sup>spec</sup>infrastructure facilities and building construction is safe for students and other staff of the school. The Structural designing has been done as per standard engineering practices in confirmation with the relevant Indian standard codes of practices and is checked for safety against earthquake as per IS - 1893 and school authorities certified that the construction has been done as per that structural drawings.


This certificate is issued after inspecting the school premises.

  
Sub Engr

  
Sub Divisional Officer  
I.W.D. (S&A) Dist. Sub Div. No. 1, INDC&E

  
कोयपालन बन्त्री  
छो.नि.वि. (म./स.) इन्दौर संक्र.।

  
Manager  
Agarwal Public School

  
Principal  
Agarwal Public School  
INDORE (M.P.)